



NOTE: MAKE 37-38-39-40-41-42 FROM Y-2-ASST.

NOTE: DRILL & DRAW HOLES TO BE DRILLED IN ALL PARTS BEFORE ANODIZING AND PRIMING. NOTE: ALL CONTOUR DIMENSIONS.

H-501

DETAIL - G CHANNEL SCALE ONE FOURTH SIZE

ALL AL ALLOY SHEET SHALL BE (3003) ALLOY 5051 ENGLISH AND ALL AL ALLOY EXTRUSIONS SHALL BE (3003) ALLOY 5051 ENGLISH. ALL AL ALLOY PARTS SHALL BE ANODIZED AND PRIMED. DRILL & DRAW HOLES TO BE DRILLED IN ALL PARTS BEFORE ANODIZING AND PRIMING.